



1/4





2/4




FIG. 2



3/4




FIG. 3





FIG. 4



4/4

$i=0$	q		$i=8$	q		$i=16$	q		$i=24$	q	
	8	16		...15	8	16	...23	8	16	8	16
$[13]$ [00]	C_0 00	C_0 0	$[33]$ [02]	C_0 01	C_2 1	$[31]$ [00]	C_5 00	C_8 0	$[11]$ [02]	C_5 01	C_{10} 1
$[12]$ [10]	C_1 00	C_1 0	$[32]$ [12]	C_1 01	C_3 1	$[30]$ [10]	C_4 00	C_9 0	$[10]$ [12]	C_4 01	C_{11} 1
$[11]$ [20]	C_0 10	C_2 0	$[31]$ [22]	C_0 11	C_0 1	$[33]$ [20]	C_5 10	C_{10} 0	$[13]$ [22]	C_5 11	C_8 1
$[10]$ [30]	C_1 10	C_3 0	$[30]$ [32]	C_1 11	C_1 1	$[32]$ [30]	C_4 10	C_{11} 0	$[12]$ [32]	C_4 11	C_9 1
$[03]$ [01]	C_3 00	C_5 0	$[23]$ [03]	C_3 01	C_7 1	$[21]$ [01]	C_6 00	C_{13} 0	$[01]$ [03]	C_6 01	C_{15} 1
$[02]$ [11]	C_2 00	C_4 0	$[22]$ [13]	C_2 01	C_6 1	$[20]$ [11]	C_7 00	C_{12} 0	$[00]$ [13]	C_7 01	C_{14} 1
$[01]$ [21]	C_3 10	C_7 0	$[21]$ [23]	C_3 11	C_5 1	$[23]$ [21]	C_6 10	C_{15} 0	$[03]$ [23]	C_6 11	C_{13} 1
$[00]$ [31]	C_2 10	C_6 0	$[20]$ [33]	C_2 11	C_4 1	$[22]$ [31]	C_7 10	C_{14} 0	$[02]$ [33]	C_7 11	C_{12} 1

FIG. 5